

SANDHILL RIVER WATERSHED DISTRICT

August 8, 1956

The board made an inspection WORD of the new bridges constructed by Thorson Construction Co. by Balaton, Minnesota. Charles Sheridan drove. The board called Thorson's attention to a little more cleaning up at some of the sites. Board agreed to meet at the county engineer's office on August 10. All motion meeting adjourned.

N. J. Mjelde, Secretary

Inspected bridge S-8 at 11:30; not enough black top.

Inspected bridge S-10; nice job except for too light of black top fill.

Inspected bridge S-13 at 12:10; not enough dirt out from under the bridges

Inspected bridge S-17 at 12:30; OK

Inspected bridge S-19 at 1:00; OK